

SNOW BROS

P2 of 2

SNOW_BROS

SOLDER SIDE	NO	NO	PARTS SIDE
GND	A	1	GND
GND	B	2	GND
+5V	C	3	+5V
+5V	D	4	+5V
	E	5	
+12V	F	6	+12V
	G	7	
	H	8	
	I	9	
SPEAKER(-)	J	10	SPEAKER(+)
	K	11	
VIDEO GREEN	L	12	VIDEO RED
VIDEO SYNC	M	13	VIDEO BLUE
	N	14	
	O	15	
COIN SW 2	P	16	COIN SW 1
2P START	Q	17	1P START
2P UP	R	18	1P UP
2P DOWN	S	19	1P DOWN
2P LEFT	T	20	1P LEFT
2P RIGHT	U	21	1P RIGHT
2P PUSH S/W1	V	22	1P PUSH S/W1
2P PUSH S/W2	W	23	1P PUSH S/W2
	X	24	
	Y	25	
	Z	26	
GND	a	27	GND
GND	b	28	GND

SNOW BROS

P393

29 276

2 2400 B PS

29 010

29 010

760827-15
(B2442)

760827-15
(B2442)

8000 P 10

(14) 6116

(12) 6116

18CVP8

6264

18CVP8
18CVP8

43 276

43 276

43 276

43 276

29 010

29 010

29 010

29 010

18CVP8

18CVP8

6264 P

18CVP8